

DOCUMENTS TO THE REQUESTOR

West Vermont Drinking Water Contamination Superfund Site \$
Weston Solutions, Inc.
Indiana

<u>Document Type</u>	<u>Date</u>	<u>Pages</u>
General Notice Letter – Gennx Properties VII LLC	09/23/2011	4
General Notice Letter – Multiple PRPS	02/17/2011	11
IDEM Letter RE: Additional Investigation Request For Genuine Parts, Michigan Plaza And Allison Transmission Plant 12	01/22/2010	2
Environ – Remedial Progress Report For Former Allison Plant 10	01/01/2012	396
Mundell & Assoc Letter RE: Quarterly Monitoring Progress Report, Fourth Quarter 2011 For Michigan Plaza	01/31/2012	258
EPA Letter RE: Request For ARARS For West Vermont Drinking Water Contamination Site	02/10/2012	2
Mundell & Assoc Letter RE: Response To IDEM's Request For Revised Remediation Work Plan Approval Review And Technical Response To General Notice Of Potential Liability Review For Michigan Plaza	03/16/2012	75
IDEM E-Mail Message RE: Revised Work Plan For 3 RD Round Of Cap For MI Plaza	05/27/2012	2
EPA – In The News-Technology Innovation News Survey: US EPA Contamination Site Cleanup Information	07/03/2012	1
Favero Geosciences – Fourth Quarter 2010 Progress Report – RCRA Corrective Action – Allison Transmission	01/14/2011	1,033

DOCUMENTS TO THE REQUESTOR

West Vermont Drinking Water Contamination Superfund Site \$
Weston Solutions, Inc.
Indiana

<u>Document Type</u>	<u>Date</u>	<u>Pages</u>
Weston Solutions Inc. – West Vermont VI Study Site Summary Letter Report	07/31/2013	55
Mundell Consulting Professionals - Remediation Work Plan – Reference No. 19	09/18/2013	1,510
Weston Solutions Inc. – Log Book - Reference No. 12	03/01/2013	43
Weston Solutions Inc – Monitoring Well Sampling Logs – Reference No. 10	11/19/2013	13
Weston Solutions Inc. – Monitoring Well Sampling Logs – Reference No. 9	10/08/2013	13
Weston Solutions Inc. – Monitoring Well Sampling Logs – Reference No. 8	09/10/2013	13
Weston Solutions Inc. – Monitoring Well Sampling Logs – Reference No. 7	08/20/2013	14
Weston Solutions Inc. – Monitoring Well Sampling Logs – Reference No. 6	07/23/2013	13
Weston Solutions Inc. – Monitoring Well Sampling Logs – Reference No. 5	06/26/2013	13
EPA – Postcard	01/01/2012	2
Weston – Site Boundary Map	02/01/2010	1
EPA Fact Sheet – Agencies Advise Municipal Water For Private Well Users (Spanish Version)	04/01/2011	2
EPA Fact Sheet – Agencies Advise Municipal Water For Private Well Users	04/01/2011	2

DOCUMENTS TO THE REQUESTOR

West Vermont Drinking Water Contamination Superfund Site \$
Weston Solutions, Inc.
Indiana

<u>Document Type</u>	<u>Date</u>	<u>Pages</u>
EPA Fact Sheet – May 25 Meeting Set To Discuss Contamination	05/01/2010	2
Mundell Consulting Professionals - Quarterly Monitoring Progress Report, 1 st Quarter, 2013 – Reference No. 28	04/30/2013	484
EPA – Enforcement Action Memorandum - Determination Of Threat To Public Health And The Environment And Selection Of Time-Critical Removal Actions – Reference No. 32	08/05/2013	27
Weston Solutions Inc. – Technical Memorandum, Analytical And Hydrogeological Evaluation – Reference No. 38	01/30/2013	448
Weston Solutions Inc. – Data Validation Report – Reference No. 47	04/19/2010	15
Favero Geosciences Letter RE: Transmittal Of Fourth Quarter 2010 Progress Report, RCRA Corrective Action, USEPA ID Nos. IND006412248 And IND0008062828 – Reference No. 48	01/14/2011	1,033
EPA Memo RE: Request For Approval And Funding For A Time-Critical Removal Action At The West Vermont Drinking Water Contamination Site, Speedway, Marion County, Indiana (Site ID #B5UJ) – Reference No. 49	09/26/2011	28
Weston Solutions Inc/Pace Analytical Services, Inc. – West Vermont Hydrogeologic Investigation, Data Validation Report – Reference No. 50	11/18/2011	290

DOCUMENTS TO THE REQUESTOR

West Vermont Drinking Water Contamination Superfund Site \$
Weston Solutions, Inc.
Indiana

<u>Document Type</u>	<u>Date</u>	<u>Pages</u>
EPA – W. Vermont Hydrological Investigation, Field Log Notes – Reference No. 51	11/09/2011	53
Weston Solutions Inc./Pace Analytical Services, Inc. – Data Validation Report – Reference No. 55	11/05/2013	71
Weston Solutions Inc./Pace Analytical Services Inc. – Data Validation Report – Reference No. 69	02/04/2014	56
Weston Solutions Inc./Pace Analytical Services Inc – Data Validation Report – Reference No. 66	01/16/2014	46
Weston Solutions Inc./Pace Analytical Services Inc – Data Validation Report – Reference No. 65	01/16/2014	28
University of Minnesota – Tetrachlorethene Pathway Map (Anaerobic) – Reference No. 64	01/01/2011	5
Weston Solutions Inc./Pace Analytical Services Inc – Data Validation Report – Reference No. 63	12/09/2013	56
Weston Solutions Inc – Monitoring Well Sampling Logs – Reference No. 62	10/08/2013	13
Weston Solutions Inc./Pace Analytical Services, Inc. – Data Validation Report – Reference No. 61	10/24/2013	33
Weston Solutions Inc. – Monitoring Well Sampling Logs – Reference No. 59	09/10/2013	13

DOCUMENTS TO THE REQUESTOR

West Vermont Drinking Water Contamination Superfund Site \$
Weston Solutions, Inc.
Indiana

<u>Document Type</u>	<u>Date</u>	<u>Pages</u>
Weston Solutions Inc/Pace Analytical Services Inc. – Data Validation Report – Reference No. 58	09/24/2013	51
Weston Solutions Inc. – Monitoring Well Sampling Logs – Reference No. 56	07/23/2013	13
Weston Solutions Inc/Pace Analytical Services Inc. – Data Validation Report – Reference No. 70	02/04/2014	26
Weston Solutions Inc. – Title Search Report For West Vermont Water Contamination Site, Genuine Auto Parts Property – Reference No. 79	06/16/2011	11
Weston Solutions Inc. – Title Search Report For West Vermont Water Contamination Site, Michigan Plaza Property – Reference No. 80	06/16/2011	12
Mundell Consulting Professionals - Quarterly Monitoring Progress Report, 4 th Quarter, 2013 – Reference No. 98	01/31/2014	593
Microseeps – 2010 Laboratory Results - Reference No. 104	07/21/2010	46
Pace Analytical – West Vermont Street, Pace Project No. 5055016 – Reference No. 105	12/24/2011	29
Weston Solutions Inc. – Boring Well Logs - Reference No. 131	11/16/2011	5
Black & Veatch – Boring Logs, Various Dates 2010 – Reference No. 128	07/02/2010	26

DOCUMENTS TO THE REQUESTOR

West Vermont Drinking Water Contamination Superfund Site \$
Weston Solutions, Inc.
Indiana

<u>Document Type</u>	<u>Date</u>	<u>Pages</u>
Mundell Consulting Professionals - Remediation Work Plan – Reference No. 121	09/18/2013	54